

**Notices to Mariners** 

No. 2025-17 14 AUGUST 2025 NOTICES: 158 - 159

AGENTSCHAP
MARITIEME
DIENSTVERLENING en
KUST

www.flemishhydrography.be

**Published by:** Administrator General Nathalie Balcaen

IAA Maritime and Coastal Services (MCS) - Brussel

2025

**Compiled by:** MCS - Coastal Division - Flemish Hydrography

Vrijhavenstraat 3 - 8400 Oostende

# © Flemish government

Reproduction of data from this publication is allowed provided the full acknowledgment is displayed: "MCS - Coastal Division - Flemish Hydrography".

This is a free translation of the official "Berichten aan Zeevarenden, nr. 2025-17" In case of dispute the Dutch text is the only valid copy.

## Positions:

are given in the reference system World Geodetic System 84 (WGS84). Incorrect interpretation of the reference system can lead to errors in the position of several hundred of metres.

# Depths (in metres):

are reduced to Lowest Astronomical Tide (LAT) for tidal areas and to local dock datum for non-tidal areas.

## Heights (in metres):

drying heights are above LAT. Vertical clearance is above Mean High Water Spring (MHWS). Other heights are above Mean Sea Level (MSL). Heights for non-tidal areas are above local dock datum.

Directions. bearings. leading lines and light sectors (in degrees): are true reckoned from seawards.



# **BELGIUM**

# 2025-17/158 COASTAL ROUTE - OOSTENDE-ZEEBRUGGE - BUOY

NtM 2025-06/102(T) is cancelled.

Charts: BE101 (INT 1474), BE11

Source: MRCC LB042/25

# **NETHERLANDS**

# 2025-17/159(T) APPROACH WESTERSCHELDE - RAAN - BUOYS

Charts: BE101 (INT 1474), BE11

## Insert:

- Buoy VR-A, yellow spar, St Andrew's cross as topmark, FI(5)Y.20s in position 51°29,36'N 003°13,52'E
  Buoy VR-C, yellow spar, St Andrew's cross as topmark, FI(5)Y.20s in position 51°31,67'N 003°17,10'E

Each buoy covers a measuring frame.

Source: GNA Bass 095-2025, Rijkswaterstaat

# MARITIME SAFETY INFORMATION (MSI) in force

#### MSI > 23/189 SEAAREA (COAST)

ZINKERLEIDING RAVERSIJDE UITGELEGD TUSSEN STRAND EN 51-13.294 N 002-51.385 E GEMARKEERD MET NOORDKARDINALE BOEI 'JDN' ZINKERLEIDING LOMBARDSIJDE UITGELEGD TUSSEN STRAND EN POS 51-10.17 N 002-45.01 E GEMARKEERD MET NOORDKARDINALE BOEI 'DC1'

#### MSI > 24/455 APPROACH BLANKENBERGE

LIGHTBUOY HB2, 51-18.81 N 003-06.22 E TEMPORARILY REMOVED

#### MSI > 24/543 OOSTENDE-ZEEBRUGGE

OBSTACLES ON THE SEABED IN FOLLOWING POS 51°17.431 N 003°02.602 E 51°17.259 N 003°02.007 E 51°16.304 N 002°59.844 E SHIPPING IS REQUESTED NOT TO ANCHOR NOR TO FISH IN THE VICINITY

#### MSI > 24/544 OOSTENDE-ZEEBRUGGE

OBSTACLES ON THE SEABED IN FOLLOWING POS 51°15.938 N 002°58.482 E 51°15.943 N 002°58.492 E SHIPPING IS REQUESTED NOT TO ANCHOR NOR TO FISH IN THE VICINITY

#### LB > 25/038 OOSTENDE-ZEEBRUGGE

LIGHTBUOY O, 51-19.59 N 003-07.66 E TEMPORARILY REMOVED

#### LB > 25/039 OOSTENDE-ZEEBRUGGE

LIGHTBUOY BA-W, 51-14.81 N 002-54.90 E TOPMARK MISSING

#### LB > 25/044 OOSTENDE-ZEEBRUGGE

FISHING GEAR LOST BY VESSEL RATAPLAN III IN THE VICINITY OF POS 51-18.390 N  $\,$  003-04.432 E MARKED BY RED BOUY

### MSI > 25/184 OOSTENDE-ZEEBRUGGE

OBSTACLES ON THE SEABED IN FOLLOWING POSITIONS 51° 17,352N 002° 56,610E 51° 17,281N 002° 56,553E SHIPPING IS REQUESTED NOT TO ANCHOR NOR FISH IN THE VICINITY

## MSI > 25/221 BE EEZ

LIGHTBUOY TME2, 51-30.82 N 002-28.81 E LIGHT UNLIT

#### MSI > 25/257 BE EEZ

AN UNPROTECTED CABLE IS ON THE SEABED BETWEEN THE FOLLOWING COORDINATES 51-21.05 N - 002-44.15 E 51-19.00 N - 002-46.44 E PROHIBITED TO ANCHOR NOR TO FISH IN THIS VICINITY GUARDVESSEL DEFENDER CALLSIGN MMKB9 IS LISTENING OUT ON VHF 16 AND 65

#### MSI > 25/277 BE EEZ

BOTTOM SURVEY BY M/V MIRANDA CALLSIGN: T7AD2 IN VICINITY OF THE AKKAERTBANK SHIPPING IS REQUESTED TO PROVIDE A MINIMUM PASSING DISTANCE OF 5 CABLES M/V MIRANDA IS LISTENING OUT ON VHF 16 AND 65

# MSI > 25/284 TSS-WESTHINDER

LIGHTBUOY AKKAERT-SW, 51-22.28 N 002-46.34 E LIGHT UNRELIABLE