

**Notices to Mariners** 

No. 2025-22 23 OCTOBER 2025 NOTICES: 176 - 177

AGENTSCHAP
MARITIEME
DIENSTVERLENING en
KUST

www.flemishhydrography.be

**Published by:** Administrator General Nathalie Balcaen

IAA Maritime and Coastal Services (MCS) - Brussel

2025

**Compiled by:** MCS - Coastal Division - Flemish Hydrography

Vrijhavenstraat 3 - 8400 Oostende

# © Flemish government

Reproduction of data from this publication is allowed provided the full acknowledgment is displayed: "MCS - Coastal Division - Flemish Hydrography".

This is a free translation of the official "Berichten aan Zeevarenden, nr. 2025-22" In case of dispute the Dutch text is the only valid copy.

## Positions:

are given in the reference system World Geodetic System 84 (WGS84). Incorrect interpretation of the reference system can lead to errors in the position of several hundred of metres.

## Depths (in metres):

are reduced to Lowest Astronomical Tide (LAT) for tidal areas and to local dock datum for non-tidal areas.

## Heights (in metres):

drying heights are above LAT. Vertical clearance is above Mean High Water Spring (MHWS). Other heights are above Mean Sea Level (MSL). Heights for non-tidal areas are above local dock datum.

Directions. bearings. leading lines and light sectors (in degrees): are true reckoned from seawards.



## **NETHERLANDS**

## 2025-22/176(T) APPROACH WESTERSCHELDE - RAAN - BUOYS

Charts: BE101 (INT 1474), BE11

## Insert:

- Buoy MP 1, yellow spar, St Andrew's cross as topmark, FI(5)Y.20s in position 51°31,42'N 003°13,33'E
- Buoy MP 2, yellow spar, St Andrew's cross as topmark, FI(5)Y.20s in position 51°30,42'N 003°15,12'E
- Buoy MP 3, yellow spar, St Andrew's cross as topmark, FI(5)Y.20s in position 51°29,23'N 003°17,09'E
- Buoy MP 4, yellow spar, St Andrew's cross as topmark, FI(5)Y.20s in position 51°28,16'N 003°19,00'E
- Buoy MP 5, yellow spar, St Andrew's cross as topmark, FI(5)Y.20s in position 51°27,07'N 003°21,00'E

Each buoy covers a measuring frame.

Source: GNA Bass 136-2025, Rijkswaterstaat

# 2025-22/177 WESTERSCHELDE - VALKENISSE-SAEFTINGE - SCHAAR VAN VALKENISSE - BUOYS

Charts: BE106 (INT 1478)

## Delete:

- Buoy REC-C in position 51°22,46'N 004°05,75'E
- Buoy REC-D in position 51°22,33'N 004°05,88'E

Source: GNA Bass 142-2025, Rijkswaterstaat

# MARITIME SAFETY INFORMATION (MSI) in force

## MSI > 23/189 SEAAREA (COAST)

ZINKERLEIDING RAVERSIJDE UITGELEGD TUSSEN STRAND EN 51-13.294 N 002-51.385 E GEMARKEERD MET NOORDKARDINALE BOEI 'JDN' ZINKERLEIDING LOMBARDSIJDE UITGELEGD TUSSEN STRAND EN POS 51-10.17 N 002-45.01 E GEMARKEERD MET NOORDKARDINALE BOEI 'DC1'

## MSI > 24/455 APPROACH BLANKENBERGE

LIGHTBUOY HB2, 51-18.81 N 003-06.22 E TEMPORARILY REMOVED

## MSI > 24/543 OOSTENDE-ZEEBRUGGE

OBSTACLES ON THE SEABED IN FOLLOWING POS 51°17.431 N 003°02.602 E 51°17.259 N 003°02.007 E 51°16.304 N 002°59.844 E SHIPPING IS REQUESTED NOT TO ANCHOR NOR TO FISH IN THE VICINITY

#### MSI > 24/544 OOSTENDE-ZEEBRUGGE

OBSTACLES ON THE SEABED IN FOLLOWING POS 51°15.938 N 002°58.482 E 51°15.943 N 002°58.492 E SHIPPING IS REQUESTED NOT TO ANCHOR NOR TO FISH IN THE VICINITY

## LB > 25/038 OOSTENDE-ZEEBRUGGE

LIGHTBUOY O, 51-19.59 N 003-07.66 E TEMPORARILY REMOVED

## LB > 25/046 PORT OF ZEEBRUGGE

THE LOWER LIGHT OF LIGHTLINE 193° IS OUT OF SERVICE UNTIL FURTHER NOTICE. VESSELS ARE REQUESTED TO PROCEED WITH CAUTION. VTS INFORMATION CAN BE OBTAINED FROM PORT CONTROL CHANNEL È&

## LB > 25/047 OUTER PORT

LIGHTBUOY ZW3, 51-21.55 N 003-11.21 E LIGHT UNLIT

## MSI > 25/184 OOSTENDE-ZEEBRUGGE

OBSTACLES ON THE SEABED IN FOLLOWING POSITIONS 51° 17,352N 002° 56,610E 51° 17,281N 002° 56,553E SHIPPING IS REQUESTED NOT TO ANCHOR NOR FISH IN THE VICINITY

## MSI > 25/304 TSS-WESTHINDER

LIGHTBUOY AKKAERT-SW, 51-22.28 N 002-46.34 E LIGHT UNRELIABLE

## MSI > 25/311 BE EEZ

EXPLOSIVE LOST ON THE LINE BETWEEN POSITIONS 51-20.04 N 003-05.47 E AND 51-20.990 N 003-03.586 E SHIPPING IS REQUESTED NOT TO ANCHOR NOR TO FISH IN THE VICINITY.

## MSI > 25/350 OOSTENDE-ZEEBRUGGE

CHAIN ON THE SEABED IN THE VICINITY OF 51-20,05N 003-03,75E SHIPPING IS REQUESTED NOT TO ANCHOR NOR TO FISH IN THE VICINITY

## MSI > 25/356 BE EEZ

OBSTACLES ON THE SEA BED IN POS 51-23.730 N 002-29.791 E AND 51-23.557 N 002-30.286 E ANCHORING AND FISHING ARE PROHIBITED WITHIN DISTANCE OF 200M

## MSI > 25/365 BE EEZ

POSSIBLE EXPLOSIVES ON THE SEABED IN AREA BOUNDED BY 51-31.75N 002-31.13E 51-20.06N 002-51.09E 51-19.93N 003-09.75E 51-19.31N 003-08.04E 51-20.06N 002-51.09E 51-31.19N 002-30.45E SHIPPING IS REQUESTED NOT TO ANCHOR NOR TO FISH IN THE VICINITY.

## MSI > 25/396 BE EEZ

LIGHTBUOY TME2, 51-30.82 N 002-28.81 E TEMPORARILY REMOVED