


Attachment to NtM 2026-08/097

2.1.2. Ankergebied Oostdyck

This area is bordered by the lines:

From position:	51°19,6000'N	002°36,0900'E
To:	51°19,6000'N	002°33,8000'E
To:	51°19,6000'N	002°33,6000'E
To:	51°19,6000'N	002°31,5000'E
To:	51°20,4000'N	002°31,5000'E
To:	51°20,5168'N	002°33,2094'E
To:	51°20,3274'N	002°38,6653'E
To:	51°19,6511'N	002°38,6844'E
To:	51°19,6436'N	002°38,6559'E



Shipping is made aware of the presence of submarine cables above the northern side of the anchorage area. There is also a submarine cable in the eastern part of the anchorage area. Ships must maintain a safe distance from these submarine cables when anchoring.